





## Priority Barriers to Fish Passage

ID#	Stream & Location
1	Coyote Creek, Casitas Dam*
2	San Antonio Creek, Fraser Street
3	San Antonio Creek, Camp Comfort
4	Matilija Creek, USGS Gauge Weir
5	Matilija Creek, Matilija Dam
6	North Fork Matilija Creek, Ojai Quarry
7	North Fork Matilija Creek, Lower Wheeler Campground Crossing
8	Bear Creek, Upper Wheeler Campground Crossing
9	Bear Creek, Lower Wheeler Campground Crossing
10	North Fork Matilija Creek, Upper Wheeler Campground Crossing

 Ventura River Watershed

 Points indicate partial fish passage barriers, based on the preliminary estimate of local experts. Many other partial barriers exist. A formal on-the-ground assessment of barriers is needed.

 Points indicate full fish passage barriers.

\* It is not expected that Casitas Dam will be removed, however regulators would like this barrier mitigated to allow for fish passage.

Data Source:  
California Fish Passage Assessment  
Database (PAD), Spring 2014  
Map Created by GreenInfo Network  
using Esri software, Oct. 2014  
[www.greeninfo.org](http://www.greeninfo.org)