



Water Quality Impairments



Ventura River Watershed

Impaired Water Body Name

- | | |
|---|--|
| █ Ventura River Estuary | █ Cañada Larga Creek |
| █ Ventura River Reaches 1, 2 | █ San Antonio Creek |
| █ Ventura River Reach 3 | █ Lake Casitas |
| █ Ventura River Reach 4 | █ Matilija Creek Reaches 1, 2 |
| | █ Matilija Reservoir |



Data Source:
Regional Water Quality Control Board Los Angeles
Map Created by GreenInfo Network using Esri software
April 2014 www.greeninfo.org